MB-Comm Version history

Version 5.4.2
1st June 2011
   - fixed: non ascii letters are printed incorrectly in chat mode if current
keyboard layout
     is not consistent with default system language

Version 5.4.1
20th May 2011
   - MB USB port is selected by default (if available) during first run after
first setup
   - build number is properly displayed in Add/Remove Program Control Panel
module and during
     installation process

Version 5.4.0
1st April 2011
   - Italian localisation and help file added
   - changed names for versions of English language during firmware update
   - fixed problem with second connection if 8 dot mode is used
   - serial port settings are changeable again
   - version information changed to: major.minor.build
   - uninstall shortcut placed in Menu Start program subfolder

Version 4.1
17th Sept. 2009
Fixed timing requirements for use with latest USB drivers (V5.4.24).
Note: The new USB drivers will not be released yet, but applied on an as needs
basis.
MB-Comm is still compatible with the older drivers.

Version 4.0
13th August 2009
Included Sri Lanka character set.

Version 3.9P
Special version for Polish language.

Version 3.9
22 May 2009
Added more error reporting and checking for uploads with respect to the Serial
number prom.

Version 3.8
18 May 2009
Improved error message handling and reporting for MB Firmware uploads.

Version 3.7
1st May 2009
Added larger buffer for communications and changed data delivery to MB. Data is
now sent and stored before allowing embossing to begin.

Version 3.6
8th August 08
Same as V3.5 except improved error checking for the MB software upgrade process
and improved error message notices.
Note: MB-comm Ver 3.6 can be used normally with the MB, but if it is used in the

User software update mode then it is mandatory to upgrade the MB User Boot
Loader
to Ver 4.0 before you use MB-Comm V3.6 for upgrading. Refer separate
instructions
or contact your dealer for doing this.

Version 3.5
29th July 08
Added function to close MB-Comm correctly if MB is switched off or disconnected
before closing MB-Comm.

Version 3.4
18th July 08
Modification for Greek MB. Added new Greek ascii code table CP1253 to show
correct Greek characters on screen.

Version 3.3
30th June 08
Pre-installer for Ver 3.2 proved troublesome -so MB-Comm and USB driver now on
separate CD. When uninstalling Ver 3.2 please make sure you also uninstall the
pre-
installer.

Version 3.2
21st April 08
Pre-installer added for USB drivers and MB-Comm to allow user choice of install.

Version 3.1
10 Dec 07
Windows Vista release and USB drivers updated to Ver 4.4 for Vista.
MB-Comm now works for XP and Vista.