

MB-Comm Version history

March 2017

Version 5.5.10

27th February 2017

- feature: serial port is configured for safe transfer by default for new installations

Version 5.5.9

7th August 2015

- fixed: minor changes for Slovenian language

Version 5.5.8

2nd July 2015

- fixed: minor UI improvements
- feature: displays build number of Mountbatten firmware

Version 5.5.6

8th January 2015

- feature: added support for Slovenian language

Version 5.5.4

28th October 2014

- fixed: problems with Arabic characters

Version 5.5.2

23rd April 2014

- fixed: problems with French ligatures
- feature: works with Latvian Mountbatten

Version 5.5.0

23rd October 2013

- fixed: some problems during chat through USB

Version 5.4.9

17th July 2012

- fixed: switching between back and forward translation in Czech version
- fixed: minor UI problems
- fixed: wrong letters embossed in Spanish version

Version 5.4.5

19th April 2012

- fixed: program crashes if there is no serial port available
- feature: font can be changed

Version 5.4.4

1st December 2011

- fixed: wrong letters embossed in Czech version
- feature: added option for slow transfer through USB port (port configuration dialog)

Version 5.4.3

30th September 2011

- fixed: error message after bootloader is updated

Version 5.4.2

1st June 2011

- fixed: non ascii letters are printed incorrectly in chat mode if current keyboard layout is not consistent with default system language

Version 5.4.1

20th May 2011

- MB USB port is selected by default (if available) during first run after first setup
- build number is properly displayed in Add/Remove Program Control Panel module and during installation process

Version 5.4.0

1st April 2011

- Italian localisation and help file added
- changed names for versions of English language during firmware update
- fixed problem with second connection if 8 dot mode is used
- serial port settings are changeable again
- version information changed to: major.minor.build
- uninstall shortcut placed in Menu Start program subfolder

Version 4.1

17th Sept. 2009

Fixed timing requirements for use with latest USB drivers (V5.4.24).

Note: The new USB drivers will not be released yet, but applied on an as needs basis. MB-Comm is still compatible with the older drivers.

Version 4.0

13th August 2009

Included Sri Lanka character set.

Version 3.9P

Special version for Polish language.

Version 3.9

22 May 2009

Added more error reporting and checking for uploads with respect to the Serial number prom.

Version 3.8

18 May 2009

Improved error message handling and reporting for MB Firmware uploads.

Version 3.7

1st May 2009

Added larger buffer for communications and changed data delivery to MB. Data is now sent and stored before allowing embossing to begin.

Version 3.6

8th August 08

Same as V3.5 except improved error checking for the MB software upgrade process and improved error message notices.

Note: MB-comm Ver 3.6 can be used normally with the MB, but if it is used in the User software update mode then it is mandatory to upgrade the MB User Boot Loader to Ver 4.0 before you use MB-Comm V3.6 for upgrading. Refer separate instructions or contact your dealer for doing this.

Version 3.5

29th July 08

Added function to close MB-Comm correctly if MB is switched off or disconnected before closing MB-Comm.

Version 3.4

18th July 08

Modification for Greek MB. Added new Greek ascii code table CP1253 to show correct Greek characters on screen.

Version 3.3

30th June 08

Pre-installer for Ver 3.2 proved troublesome -so MB-Comm and USB driver now on separate CD. When uninstalling Ver 3.2 please make sure you also uninstall the pre-installer.

Version 3.2

21st April 08

Pre-installer added for USB drivers and MB-Comm to allow user choice of install.

Version 3.1

10 Dec 07

Windows Vista release and USB drivers updated to Ver 4.4 for Vista.

MB-Comm now works for XP and Vista.